



U.S. Department of
Transportation

**Federal Motor
Carrier Safety
Administration**

EDWARD RUMBALL
PRESIDENT
LINE-DRIVE TRANSPORTATION INC
2293 SECORD AVE
WINDSOR ON N9B1T3

400 Seventh St., S.W.
Washington, D.C. 20590
August 10, 2004

In reply refer to:
USDOT Number: 1274224

Dear EDWARD RUMBALL:.

Your application seeking federal registration to operate in interstate commerce has been approved. Your USDOT number, personal identification number (PIN) and MC number, if applicable, can be found in the upper right hand corner of this letter. The USDOT number should be marked on your commercial motor vehicles as required by Section 390.21 of the Federal Motor Carrier Safety Regulations (FMCSRs). A copy of this regulation is enclosed.

As a new entrant, the Federal Motor Carrier Safety Administration (FMCSA) will evaluate your safety management practices through a safety audit and monitor your on-road performance for 18 months prior to granting you permanent registration. You must maintain adequate safety standards and comply with the FMCSRs and applicable Hazardous Materials Regulations (HMRs) in order to continue operating in interstate commerce during and after this 18-month period. Failure to comply with these requirements may result in the revocation of your New Entrant or permanent registration authority.

You must contact your local FMCSA Division office (517-702-1860) within 90 days of the date of this letter. Once contact has been made, a Safety Audit will be scheduled at the earliest possible opportunity. The purpose of the safety audit is to provide you with educational and technical assistance and to gather safety data needed to make an assessment of your safety performance and adequacy of your basic safety management controls. The auditor will review a sample of your safety management systems and a sample of required records to assess compliance with the FMCSRs, applicable HMRs and related record-keeping requirements specified in Appendix A of Part 385 of Title 49 of the Code of Federal Regulations (49 CFR Part 385). Upon completion of the audit, the auditor will review the findings with you. This discussion will be followed up within 45 days with a letter advising you whether or not FMCSA has determined that you have adequate basic safety management controls.

Failure to contact the FMCSA office within 90 days of the date of this letter may be considered a failure to permit a safety audit under section 395.337. In accordance with 49 CFR 385.337, failure to permit a safety audit to be performed on your operations may result in the revocation of your registration and/or the penalty provisions in 49 U.S.C. 521(b)(2)(A).

Please note that you are required to file an updated motor carrier registration form, the MCS-150 (Motor Carrier Identification Report), every two years. A copy of this regulation is enclosed. However, motor carriers registering commercial motor vehicles in a State participating in the Performance and Registration Information Systems Management (PRISM) Program must update their MCS-150 information with each registration renewal or as requested by the State.

(Over)